



INFORMATION LETTER

IL_GEN-13-127
18 February 2013

TO: All Bell helicopter owners and operators.

SUBJECT: PRODUCT SERVICE LETTER, INTRODUCTION.

With the introduction of the new VISTA portal, a Product Service Letter (PSL) number is required to claim warranty for bulletins.

Future bulletins with warranty will contain the PSL number in the bulletin.

The table below list current bulletins with warranty available and the associated PSL number.

Product Service Letter ID	Service Directive number	Validity period
7000000003	ASB_ 206L-07-147_ Rev_A	12/31/2014
7000000004	ASB_ 206L-09-159-RA	07/27/2014
7000000005	ASB_ 214-13-74	03/31/2013
7000000006	ASB_ 214ST-13-90	03/31/2013
7000000007	ASB_ 407-07-79A	12/31/2014
7000000008	TB_ 206-12-201 (S/N 4 - 1251)	12/31/2013
7000000010	TB_ 206-12-201 (S/N 1252 - 3216)	12/31/2013
7000000012	TB_ 206-12-201 (S/N 3217 - 44719)	12/31/2013
7000000013	TB_ 429-12-25	03/31/2013

For questions regarding this letter, please contact:

Bell Helicopter Warranty Department.
817-280-3406 / warranty@bh.com